

- 2. "X" DENOTES WIREING CONNECTION TO THE P.C. BOARD, 3. ..... DENOTES MECHANICAL CONNECTION TO METER.
- \*(F- 2 3A FUSE, 110V/1A Sio-Bio, 22V)

Figure 9
Wiring Schematic




Figure 10 Control Unit - Front Panel